

WOOD SCREWS, CLEARANCE and THREAD HOLE SIZES

Gauge of Screw	Clearance Hole inch	Thread Hole inch
0000		
000	1/16	1/32
00		
0	5/64	3/64
1	5/64	3/64
2	3/32	1/16
3	7/64	1/16
4	1/8	5/64
5	1/8	5/64
6	5/32	5/64
7	5/32	3/32
8	3/16	3/32
9	3/16	1/8
10	7/32	1/8
11	7/32	1/8
12	1/4	1/8
13	1/4	5/32
14	1/4	5/32
15	9/32	5/32
16	9/32	3/16
17	5/16	3/16
18	5/16	3/16
20	11/32	7/32
22	3/8	7/32
24	7/16	1/4
26	7/16	1/4
28	1/2	9/32
30	1/2	9/32
32	9/16	5/16
36	5/8	11/32
40	11/16	3/8
50	13/16	7/16